

HAMPTON 235/025
NH 1A over HAMPTON RIVER

Owner: NHDOT
Inspection Team: C
Bridge Maintenance Crew: 15

Wednesday, March 03, 2021

GLAND PULLED OUT OF
POSITION. TYPICAL OF ALL.
(RL)

C612 02



Wednesday, March 03, 2021

WALKWAY AT GRID IS
HEAVILY RUSTED, RAISED
AND CRACKED. (RL)

C612 03



HAMPTON 235/025
NH 1A over HAMPTON RIVER

Owner: NHDOT
Inspection Team: C
Bridge Maintenance Crew: 15

Thursday, July 23, 2020

PIER #1 NUTS MISSING AT BEARING.



C606 59

Thursday, July 23, 2020

PACK RUST AT GIRDER.



C606 60

Thursday, July 23, 2020

LIGHT POLE MISSING.



C606 61

HAMPTON 235/025
NH 1A over HAMPTON RIVER

Owner: NHDOT
Inspection Team: C
Bridge Maintenance Crew: 15

Thursday, July 23, 2020

PANELS AT UNDER
SIDEWALK HOLED.

C606 62



Thursday, July 23, 2020

PLATFORM IS RUSTED AND
HOLED.

C606 63



Thursday, July 23, 2020

CRACKED WELD AT
BEARING AT PIER #9.

C606 64



HAMPTON 235/025
NH 1A over HAMPTON RIVER

Owner: NHDOT
Inspection Team: C
Bridge Maintenance Crew: 15

Thursday, July 23, 2020

CROSS BRACING HOLED AT
SPAN #10.

C606 65

